



Accelerometers with external charge amplifiers




MI = Mineral integral
 Certified products versions for use in potentially explosive atmospheres are available.

Accelerometers with built-in or attached electronics



MI = Mineral integral
 Certified products versions for use in potentially explosive atmospheres are available.

Dynamic pressure sensors for combustion monitoring



GSI 124 galvanic separation unit

- Power supply for 2-wire transmission systems installed in potentially explosive environments
- AC signal transmission over long distances (1'000 m)
- Galvanic separation, 4 kVRMS
- High rejection of frame voltage
- DIN-rail mounting
- Ex certified versions

IPC 704 conditioners

- Signal conditioner for CA and CP sensors
- Configurable high and low-pass filters. Freq. range 0.5 Hz to 20 kHz
- Optional integrator for a velocity signal output
- Optional 2-wire current or 3-wire voltage transmission
- Ex certified versions

MI = Mineral integral
Certified products versions for use in potentially explosive atmospheres are available.